



Construction Management And Inspection

Bowman WTP Filter Gallery Improvements Placer County Water Agency



PROJECT OVERVIEW

ICM Group, Inc., teamed with Domenichelli & Associates, provided inspection services during the construction of improvements at the Bowman Water Treatment Plant Filter Gallery. This project consisted of excavation underneath existing water utility piping and constructing a steel frame metal enclosure to house the existing valve gallery. All work was performed while the treatment plant remained operational.

Bear Creek Pipeline Calaveras County Water District

PROJECT OVERVIEW

ICM Group, Inc., teamed with Domenichelli & Associates, performed construction inspection for the Bear Creek Pipeline project. The project is 20 miles east of West Point. The pipeline consisted of 9,800 lineal feet of 18-inch HDPE water force main, replacing an existing 10-inch raw water pipeline servicing Calaveras County. The pipeline was installed in very difficult foothill terrain with high groundwater and numerous stream crossings.

