



Construction Management and Inspection



Fair Oaks 40" Pipeline Relining Project

Project Data

Owner:
San Juan Water District

Project Type:
Water Pipeline

Project Duration:
Oct 2018 – May 2019

Construction Value:
\$2 Million

Inspection:
ICM Group, Inc.

Designer:
Quincy Engineering

Contractor:
J Fletcher Creamer & Sons

PROJECT OVERVIEW

The Project consisted of relining 2 miles of a 40 inch tar-coated, mortar-lined steel pipeline. The pipeline ran through residential neighborhoods, fields, commercial centers, and a ravine. Inspection was performed on the pipe installation, bedding and backfill, shoring, and traffic control.

SERVICES PROVIDED

ICM Group, Inc. provided construction management, inspection, and document control services. Our services included inspection of construction materials and methods, monthly updates for District managers, change order review and processing, claims mitigation, processing RFIs and submittals, progress payments, traffic control & public safety.